

# SBD Manufacturing and Distribution



## Deficient Components List

For Assembly: MOWER-164W Revision Number: 0

Units to Assemble: 200.00

<u>Component ID</u>	<u>Item Description</u>	<u>Quantity Needed</u>	<u>Quantity On Hand</u>	<u>Quantity Available</u>
PTHANDLE-ASSEM	4' Handle Assembly	200.00	0.00	0.00
PTWHEEL-10	10" Wheel	400.00	70.00	70.00
PTWHEEL-6	6" Wheel	400.00	70.00	70.00
PTBLADE-16-5	16" 5 blade assembly	200.00	0.00	0.00
PTNUT- 5/16	Hex nut 5/16"	1,200.00	1,180.00	1,180.00
OVER-DIRECT	Direct labor	300.00	0.00	0.00
OVER-INDIRECT	Allocated indirect costs	200.00	0.00	0.00
OVER-SUPPLIES	Allocated supplies	200.00	0.00	0.00